

Hall Function Space

Reinstatement of Period Features

Retain and make good the existing wall timber lining boards. Damaged boards to be replaced.

Air Conditioning to be hidden within flat ceiling space of Cathedral roof.

Retain and make good the existing ceiling timber lining boards.




Historical image of original hall finishes

Light fittings to be replaced.

Retain and make good the existing panelled doors.

Reinstate the Western brick wall to look like the Eastern wall with timber lining boards. Existing brick wall to be lined with white timber lining boards.



Example of Timber Lining Boards



Historical image of proscenium arch



Image Source: Trentham Irish Set Dancing Weekend Facebook Page



Image Source: Trentham Irish Set Dancing Weekend Facebook Page



Ventilation grills to be retained and reused for AC.

Salvage Proscenium Arch to be Reused or Preserved

Existing brick wall to be lined with white timber lining boards.

Building Exterior

Reinstatement of Period Features



Reinstate original galvanised zinc roof.



Historical exterior image

Original 12-pane glass window to be reinstated.